YAESU
The radio

2/1/21

FT-891 Firmware Update Information

The latest versions are listed below with the release dates.
- **MAIN Firmware Version 01-09 (2/01/21)**
- **DSP Firmware Version 02-04 (2/01/21)**
- **Panel Firmware Version 01-01 (9/06/17)**

*If you already have the above listed firmware versions, it is not necessary to update the FT-891 again.

There are three different firmware installations. Each one must be followed carefully. Installing the wrong type firmware may cause difficulties. Check your radio before installing firmware to be sure which updates are needed. **Please read the FT-891 Firmware Upgrade Manual before proceeding.**

Before installing new firmware, please verify your current version firmware with the following procedure:

How to Confirm the Current Firmware Version of the transceiver

MAIN, DSP, and LCD(Panel) firmware are available for FT-891 transceiver. Check the firmware version, and perform firmware updates when needed.
1. Press and hold the **[PWR/LOCK]** key to turn the transceiver ON.
2. Press and hold the **[F]** key to activate the Menu mode.
3. Rotate the MULTI function knob to select Menu Mode "**18-01 [MAIN VERSION]**", "**18-02 [DSP VERSION]**" or "**18-03 [LCD VERSION]**".
   The firmware versions will be displayed on the LCD screen.

```
MENU       18-01    VERSION
RESET               FACTORY
MAIN VERSION        V**-**
DSP VERSION         V**-**
LCD VERSION         V**-**
```

(This image & version is for illustration only)

Download the FT-891 data and [**FT-891_Firmware_Update_2021_02.zip**] from the following website:
https://www.yaesu.com/indexVS.cfm?cmd=DisplayProducts&ProdCatID=102&encProdID=DF4DB2 62968932E999EAF928B5B6A1A7&DivisionID=65&isArchived=0

The zip file contains all of the current software versions. Please verify which version software is already on your radio before updating. If you have each of the listed versions, you do not need to update the radio again.

Name	Type
Ah065_m_v0109.sfl	SFL File
Ah065_p_v0101.sfl	SFL File
AH065_V0204.dat	DAT File
YFSW023.exe	Application
FT-891_Firmware_Ver_Up_Manual_ENG.pdf	Adobe Acrobat Document

Please read the FT-891 Firmware Upgrade Manual before proceeding!

Implements improvements

MAIN Firmware Version 01-09 (2/01/21)
DSP Firmware Version 02-04 (2/01/21)

1. Fixed a bug that the S meter may not indicate to the received signal level.
2. Improved and optimized additional functions.

We hope this new firmware will increase your enjoyment of your FT-891. Thank you for choosing Yaesu radios. If you have any problems or questions, please contact Yaesu Amateur Tech Support amateurtech@yaesu.com.

Best regards,